



Reviewed by: Clay Altizer, FRA Southwide Region Manager, caltizer@forestresources.org



BACKGROUND

A logging crew was working in the Southeastern United States on a hurricane salvage tract. The harvest site presented hazards common with this type of operation: numerous broken trees with downed stems that were blown over or laying on the ground (many of which were still partially anchored into the ground with their roots with stems under tension).

PERSONAL CHARACTERISTICS

The skidder operator has been part of this logging crew for five years but had less than one year of experience on the skidder at the time of the accident. He is considered a safe, reliable, and hardworking member of the crew. This crew has not had an incident like this in over 10 years.

ACCIDENT

The crew had been working for a few months and was finishing up at a brow before moving to the next location on the tract. The feller-buncher operator had the skidder follow him through the harvest area to help ensure they could locate remaining drags in the rear of the tract. With the skidder following close behind, the feller-buncher operator articulated the machine to avoid debris in its path. The back tire of the buncher clipped a root-ball, releasing a 50-foot long, 10-inch diameter stem that ended up in the path of the skidder. The skidder driver had little time to react and brake only enough time to let-off the throttle. The large stem grazed the front left tire then penetrated the window of the cab.

INJURY

The operator was aware that the stem was crashing through the window of the cab and was able to avoid a major injury by vacating his seat. The butt of the stem came to rest in the operator’s seat. The skidder driver sustained some sore ribs and missed a week of work.

RECOMMENDATIONS FOR CORRECTIONS

-
-
-
-
-



This Safety Alert analyzes an injury in accordance with the chain of events represented by the five dominoes above. Pioneer industry safety experts H.W. Heinrich and Alfred Lateiner developed this accident analysis system to provide a graphic sense of how injuries can be avoided. Their methodology has been accepted by safety professionals worldwide.

Safety Meeting Report

Topic(s) Discussed:

Comments / Recommendations:

Date:

Company:

Names of Employees Attending:

Meeting Conducted by:

Please follow equipment manufacturers' recommendations for safe operation and maintenance procedures.

signature